

ELVITA

Technical document

This document is only intended for internal use and for authorized service partners.

Product category:	Tumbledryer
Affected models:	CTT7800V, CTT7100V
Release:	1.0, 2024-10-08

Additional spare part recommended when replacing driving belt on the motor

Description:

On these models, the driving belt for the motor is missing as a separate part

Action:

If the driving belt needs to be replaced, please use article F659422

Required spare parts:	<ul style="list-style-type: none">• Drive Belt - F659422
------------------------------	--

This document is only intended for internal use and for authorized service partners.