

ELVITA

Technical document

This document is only intended for internal use and for authorized service partners.

Product category:	Tumbledryer
Affected models:	CTT7800V, CTT7100V
Release:	1.0, 2023-04-03

Additional spare part recommended when replacing motor

Description:

Since the old fan assembly is hard to remove without damaging it, we recommend that the fan assembly is ordered when replacing the motor.

Action:

When replacing the motor (W375325 / 110020150113568) we also recommend ordering the fan assembly (R870117 / 12138200003601).

Required spare parts:	<ul style="list-style-type: none">Fan assembly - R870117 / 12138200003601
------------------------------	-----------------------------------------------------------------------------------------

This document is only intended for internal use and for authorized service partners.